Photographs



Photo 1 of 26 Main house (#4) and flower garden, looking north.




Photo 2 of 26 Old Jonesville Road (#3), looking south across intersection with Old Gainesville Road (#2).



Photo 3 of 26 Old Gainesville Road (#2), looking east.

Photo 4 of 26 Old Gainesville Road (#2), looking west, showing fence along west pasture.



Photo 5 of 26 Fenced lane along western edge of farm complex, looking north.

Dudley FarmUnited States Department of the Interior, National Park Service



Photo 6 of 26 Pasture to the north of the farm complex, looking east from road leading north from farm complex; wooded area containing stone wall (#37) and a cave entrance on the left.



Photo 7 of 26 Wood fence between abandoned fields in the northwest part of the farm, looking south.



Photo 8 of 26 Flower garden and flower pit (#5), looking southeast from near west elevation of main house (#4).



Photo 9 of 26 Cistern (#8) and east and north elevations of main house (#4), looking southwest.



Photo 10 of 26 Rear yard of main house (#4), looking east, showing kitchen (#9) on left, dairy/canning shed (#11) in background, cistern (#8), and main house (#4) on right.



Photo 11 of 26 Dairy/canning shed (#11), looking east.



Photo 12 of 26 Kitchen (#9) in foreground and smokehouse (#10) in background, looking northeast.



Photo 13 of 26 East chicken yards, looking east, showing brooder house (#12) in foreground and east chicken coop (#13) in background.



Photo 14 of 26 Domestic outbuildings, looking southeast from mule lot, showing (L to R), brooder house (#12), men's outhouse (#16), smokehouse (#10), kitchen (#9), and main house (#4).



Photo 15 of 26 Mule lot, looking southwest, showing horse stable (#19) in foreground and milk/feed room (#18) in background.




Photo 16 of 26 Mule lot, looking north showing corn crib (#20) on left, hay barn (#22) in background center, and mule stable (#21) on right.



Photo 17 of 26 Hay barn (#22), looking southeast from road along western edge of farm complex.



Photo 18 of 26 Well (#17), cotton house site, and packhouse/store (#27), looking west.



Photo 19 of 26 Cane mill (#24), cane syrup house (#25), sweet potato cellar (#26), and packhouse/store (#27), looking northwest; small chicken coop (#15) and garden in background.



Photo 20 of 26 Cane mill (#24), pump house (#23), scuppernong arbor (#32), in fenced garden behind cane mill, and tobacco barn (#28), looking south towards Old Gainesville Road (#2) and southern edge of farm complex.



Photo 21 of 26 Looking northeast from tobacco barn (#28) towards farm complex, showing scuppernong arbor (#32), vegetable garden, cane mill (#24), cane house (#25), and sweet potato cellar (#26).



Photo 22 of 26 Tobacco barn (background) and southern edge of fenced lane (entrance in foreground), looking east along Old Gainesville Road (#2).




Photo 23 of 26 Cattle dipping vat (#28), looking south from drain pad.




Photo 24 of 26 Main house (#4), interior, looking northwest from front door towards southwest room and stairs to second floor.



Photo 25 of 26 Main house (#4), interior, looking south in center corridor towards front door.




Photo 26 of 26 Main house (#4), interior, southeast room (parlor), looking northeast.